



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 20, 2011

Reviewed: 

Mine Name: Torrey Red Quarries	Permit Number: S0550021
Operator Name: State Stone Corp Inc.	Inspection Date: April 19, 2011 April 20, 2011
Inspector(s): Wayne Western	Time: 5:00 – 5:15 PM on April 19, 2011 4:00 – 4:20 PM on April 20, 2011
Other Participants:	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspection Summary:

The bond is for \$13,500 and the site is permitted for 5 acres. The bond is due for renewal on September 22, 2010.

East Side Pit: The site appeared stable. There was no sign of recent activities on the east side pit. Some minor rills were observed, but none appeared to go off site.


There was what appeared to be drilling and blasting of the bedrock. Roads were constructed to get to the top of the ridges/outcrops.

West Side Pit: The pit was active at time of inspection. The Operator was screening materials. The site was stable.

Conclusions and Recommendations:

The Division should have the Operator increase the bond.

Inspector's Signature


A handwritten signature in black ink, appearing to read "Wayne White", written over a horizontal line.

WHW

cc: (OPERATOR)

Sue_Fivecoat@blm.gov

O:\M055-Wayne\S0550021-StateStone\inspections\Insp-04192011.doc



Road leading to quarry east side



Overview of equipment storage area east pit.



Stockpiles and equipment west pit



Screening equipment west pit